BDE SPECIAL PROVISIONS For The June 11, 2004 Letting

The following special provisions indicated by an "x" are applicable to this contract and will be included by the Project Development and Implementation Section of the BD&E. An * indicates a new or revised special provision for the letting.

80099 1 1 Accessible Pedestrian Signals (APS) April 1, 2003 80011 2 Additional Bilder Responsibility Jan. 1, 2004 80076 4 Aljusting Frames and Grates Aug. 1, 2001 80076 4 Allowable Lane Differential July 1, 2002 80003 5 Articulated Block Revelment Mat Jun 1, 2003 80108 6 Asbestos Bearing Pad Removal Nov. 1, 2003 72541 7 Asbestos Waterprofing Membrane and Asbestos Bituminous June 1, 1989 June 1, 1989 80065 8 Bituminous Case CourseWildening Superpave April 1, 2002 April 1, 2004 80050 9 Bituminous Case CourseWildening Superpave April 1, 2002 April 1, 2004 80066 10 Bridge Deck Construction April 1, 2004 April 1, 2004 50261 11 Building Removal-Case II (Non-Friable Asbestos) Sept. 1, 1990 Aug. 1, 2001 50481 12 Building Removal-Case II (Non-Friable Asbestos) Sept. 1, 1990 Aug. 1, 2001 50531 14 Building Removal-Case IV (No Asbestos) Sept. 1, 1990 Aug. 1, 2001 80011 15 Catioum Chloride Accelerator for Portland Cement Concrete Patching April 1, 2004	File Name	<u>#</u>	Special Provision Title	Effective	Revised
80052 3 Adjusting Frames and Grates Aug. 1, 2001 80076 4 Allowable Lane Differential July 1, 2002 80078 5 Articulated Block Revement Mat Jan. 1, 2003 80108 6 Asbestos Bearing Pad Removal Nov. 1, 2003 7254 7 Asbestos Waterproofing Membrane and Asbestos Bituminous June 1, 1989 80065 8 Bituminous Concrete Surface Course April 1, 2002 80066 10 Bituminous Concrete Surface Course April 1, 2002 80066 10 Bridge Deck Construction April 1, 2002 50261 11 Building Removal-Case II (Non-Friable Asbestos) Sept. 1, 1990 Aug. 1, 2001 50481 12 Building Removal-Case II (Non-Friable Asbestos) Sept. 1, 1990 Aug. 1, 2001 50481 13 Building Removal-Case II (Non-Friable Asbestos) Sept. 1, 1990 Aug. 1, 2001 50531 14 Building Removal-Case II (Non-Friable Asbestos) Sept. 1, 1990 Aug. 1, 2001 80071 15 Butt Joints Sunt Joints April 1, 2004 80071 16 Calcium Chloride Accelerator for Portland Cement Concrete Patching Nov. 1, 2002 80071 17 Chair Supports	80099	1	Accessible Pedestrian Signals (APS)	April 1, 2003	
80076 4 Allówable Lane Differential Juý 1, 2002 8003 5 Articulated Block Revetment Mat Jan. 1, 2003 80108 6 Asbestos Bearing Pad Removal Nov. 1, 2003 72541 7 Asbestos Waterproofing Membrane and Asbestos Bituminous June 1, 1989 June 30, 1994 80065 8 Bituminous Base Course/Widening Superpave April 1, 2001 April 1, 2002 April 1, 2002 April 1, 2003 April 1, 2003 April 1, 2003 April 1, 2004 April 1, 2003 April 1, 2004 April 1, 2003 April 1, 2004 April	80111	2	Additional Bidder Responsibility	Jan. 1, 2004	
80093 5 Articulated Block Revetment Mat Nov. 1, 2003 80108 6 Asbestos Bearing Pad Removal Nov. 1, 2003 72541 7 Asbestos Waterproofing Membrane and Asbestos Bituminous June 1, 1989 June 30,1994 80065 8 Bituminous Concrete Surface Course April 1, 2002 April 1, 2004	80052	3	Adjusting Frames and Grates	Aug. 1, 2001	Nov. 1, 2001
Asbestos Bearing Pad Removal June 1, 1989 June 30,1994	80076	4	Allowable Lane Differential	July 1, 2002	
Asbestos Waterproofing Membrane and Asbestos Bituminous	80093	5	Articulated Block Revetment Mat	Jan. 1, 2003	
Concrete Surface Removal Bituminous Base Course/Widening Superpave April 1, 2002 April 1, 2001 April 1, 2002 April 1, 2003 April 1, 2001 April 1, 2001 April 1, 2003 April 1, 2001 April 1, 2004 April 1, 2001 April 1, 2004 April 1, 2001 April 1, 2003 April 1, 2004 April 1, 2003 April 1, 2003 April 1, 2003 April	80108	6	Asbestos Bearing Pad Removal	Nov. 1, 2003	
Concrete Surface Removal	72541	7	Asbestos Waterproofing Membrane and Asbestos Bituminous	June 1, 1989	June 30,1994
80050 9 Sough Student Sourage Course Sourage So			Concrete Surface Removal		
80066 10 Bridge Deck Construction April 1, 2002 April 1, 2002 April 1, 2002 April 1, 2002 April 1, 2004 Aug. 1, 2001 50481 12 Building Removal-Case II (Kon-Friable Asbestos) Sept. 1, 1990 Aug. 1, 2001 Aug. 1, 2002 Aug. 1, 2001 Aug. 1, 2002 Aug. 1, 2002 Aug. 1, 2003 Aug. 1, 2003 Aug. 1, 2003 Aug. 1, 2004 Aug. 1, 2003 Aug. 1, 2004 Aug. 1, 2003 Aug. 1, 2004	80065	8	Bituminous Base Course/Widening Superpave	April 1, 2002	April 1, 2004
5026I 11 Building Removal-Case I (Non-Friable and Friable Asbestos) Sept. 1, 1990 Aug. 1, 2001 5048I 12 Building Removal-Case II (Non-Friable Asbestos) Sept. 1, 1990 Aug. 1, 2001 5053I 14 Building Removal-Case IV (No Asbestos) Sept. 1, 1990 Aug. 1, 2001 80118 15 Butt Joints April 1, 2004 80031 16 Calcium Chloride Accelerator for Portland Cement Concrete Patching Jan. 1, 2001 80077 17 Chair Supports Nov. 1, 2002 80051 18 Coarse Aggregate for Trench Backfill, Backfill and Bedding April 1, 2001 80078 19 Concrete Admixtures Jan. 1, 2003 80112 20 Concrete Admixtures Jan. 1, 2004 80112 21 Controlled Aggregate Mixing System Nov. 1, 2002 80112 22 Corrugated Metal Pipe Culverts Aug. 1, 2003 80113 23 Curb Ramps for Sidewalk Jan. 1, 2004 80114 24 Curing and Protection of Concrete Construction Jan. 1, 2004 80115 25	80050	9	Bituminous Concrete Surface Course	April 1, 2001	
South 12	80066	10	Bridge Deck Construction	April 1, 2002	April 1, 2004
Sody	50261	11	Building Removal-Case I (Non-Friable and Friable Asbestos)	Sept. 1, 1990	Aug. 1, 2001
Sob31	50481	12	Building Removal-Case II (Non-Friable Asbestos)	Sept. 1, 1990	Aug. 1, 2001
Bott Some	50491	13	Building Removal-Case III (Friable Asbestos)	Sept. 1, 1990	Aug. 1, 2001
S0031 16	50531	14	Building Removal-Case IV (No Asbestos)	Sept. 1, 1990	Aug. 1, 2001
80031 16	80118	15	Butt Joints	April 1, 2004	•
80077 17 Chair Supports Nov. 1, 2002 Nov. 2, 2020 80051 18 Coarse Aggregate for Trench Backfill, Backfill and Bedding April 1, 2001 Nov. 1, 2003 80112 20 Concrete Admixtures Jan. 1, 2004 80172 21 Controlled Aggregate Mixing System Nov. 1, 2003 80103 21 Controlled Aggregate Mixing System Aug. 1, 2003 80113 23 Curb Ramps for Sidewalk Jan. 1, 2004 80114 24 Curing and Protection of Concrete Construction Jan. 1, 2004 80114 24 Curing and Protection of Concrete Construction Sept. 1, 2000 43761 26 Disadvantaged Business Enterprise Participation Sept. 1, 2000 43761 26 Driving Guardrail Posts April 1, 1998 80100 27 Epoxy Coatings for Steel Reinforcement April 1, 1997 80110 29 Epoxy Pavement Marking Jan. 1, 2001 80055 30 Erosion and Sediment Control Deficiency Deduction Aug. 1, 2001 80103 31 Expansion Joints <t< td=""><td>80031</td><td>16</td><td>Calcium Chloride Accelerator for Portland Cement Concrete Patching</td><td></td><td></td></t<>	80031	16	Calcium Chloride Accelerator for Portland Cement Concrete Patching		
80051 18 Coarse Aggregate for Trench Backfill, Backfill and Bedding April 1, 2001 Nov. 1, 2003 80112 20 Concrete Admixtures Jan. 1, 2004 80078 21 Controlled Aggregate Mixing System Nov. 1, 2002 80102 22 Corrugated Metal Pipe Culverts Aug. 1, 2003 80113 23 Curb Ramps for Sidewalk Jan. 1, 2004 80114 24 Curing and Protection of Concrete Construction Jan. 1, 2004 * 80029 25 Disadvantaged Business Enterprise Participation Sept. 1, 2000 June 1, 2004 43761 26 Driving Guardrail Posts April 1, 1998 April 1, 1998 80100 27 Epoxy Coatings for Steel Reinforcement April 1, 1997 Jan. 1, 2003 80041 29 Epoxy Powement Marking Jan. 1, 2001 Aug. 1, 2003 80055 30 Erosion and Sediment Control Deficiency Deduction Aug. 1, 2001 Nov. 1, 2001 80103 31 Expansion Joints April 1, 2003 Nov. 1, 2003 80079 33 Freeze-Thaw Rating N	80077	17	Chair Supports		Nov. 2, 2002
80094 19 Concrete Admixtures Jan. 1, 2003 Jan. 1, 2004 80172 20 Concrete Barrier Jan. 1, 2004 80078 21 Controlled Aggregate Mixing System Nov. 1, 2002 80102 22 Corrugated Metal Pipe Culverts Aug. 1, 2003 80113 23 Curb Ramps for Sidewalk Jan. 1, 2004 80141 24 Curing and Protection of Concrete Construction Jan. 1, 2004 * 80029 25 Disadvantaged Business Enterprise Participation Sept. 1, 2000 June 1, 2004 * 43761 26 Driving Guardrail Posts April 1, 1998 April 1, 1998 80100 27 Epoxy Coatings for Steel Reinforcement April 1, 1997 Jan. 1, 2003 80041 29 Epoxy Pavement Marking Jan. 1, 2001 Aug. 1, 2003 80055 30 Erosion and Sediment Control Deficiency Deduction Aug. 1, 2001 Aug. 1, 2003 80103 31 Flagger Vests April 1, 2003 Nov. 1, 2003 80079 33 Freeze-Thaw Rating Nov. 1, 2002 Nov. 1, 2002 <td>80051</td> <td>18</td> <td>Coarse Aggregate for Trench Backfill, Backfill and Bedding</td> <td></td> <td>Nov. 1, 2003</td>	80051	18	Coarse Aggregate for Trench Backfill, Backfill and Bedding		Nov. 1, 2003
80078 21 Controlled Aggregate Mixing System Nov. 1, 2002 80102 22 Corrugated Metal Pipe Culverts Aug. 1, 2003 80113 23 Curb Ramps for Sidewalk Jan. 1, 2004 80114 24 Curing and Protection of Concrete Construction Jan. 1, 2004 * 80029 25 Disadvantaged Business Enterprise Participation Sept. 1, 2000 June 1, 2004 43761 26 Driving Guardrail Posts April 1, 1998 April 1, 2003 80100 27 Epoxy Coatings for Steel Reinforcement April 1, 2003 April 1, 2003 80041 29 Epoxy Pavement Marking Jan. 1, 2001 Aug. 1, 2003 80053 30 Erosion and Sediment Control Deficiency Deduction Aug. 1, 2003 Aug. 1, 2003 80101 31 Expansion Joints April 1, 2003 Aug. 1, 2003 80103 31 Expansion Joints April 1, 2003 80104 25 Freeze-Thaw Rating Nov. 1, 2003 80105 36 Freeze-Thaw Rating Nov. 1, 2002 80072 3	80094	19		•	Jan. 1, 2004
80078 21 Controlled Aggregate Mixing System Nov. 1, 2002 80102 22 Corrugated Metail Pipe Culverts Aug. 1, 2003 80113 23 Curb Ramps for Sidewalk Jan. 1, 2004 80114 24 Curing and Protection of Concrete Construction Jan. 1, 2004 * 80029 25 Disadvantaged Business Enterprise Participation Sept. 1, 2000 June 1, 2004 43761 26 Driving Guardrail Posts April 1, 1998 April 1, 2003 80100 27 Epoxy Coatings for Steel Reinforcement April 1, 2003 April 1, 2003 80041 29 Epoxy Coating on Reinforcement April 1, 1997 Jan. 1, 2003 80041 29 Epoxy Pavement Marking Jan. 1, 2001 Aug. 1, 2003 80053 30 Erossion and Sediment Control Deficiency Deduction Aug. 1, 2001 Nov. 1, 2003 80103 31 Expansion Joints Aug. 1, 2003 April 1, 2003 80104 32 Flagger Vests April 1, 2003 April 1, 2003 80107 34 Furnished Excavation <t< td=""><td>80112</td><td>20</td><td>Concrete Barrier</td><td></td><td></td></t<>	80112	20	Concrete Barrier		
80102 22 Corrugated Metal Pipe Culverts Aug. 1, 2003 80113 23 Curb Ramps for Sidewalk Jan. 1, 2004 * 80029 25 Disadvantaged Business Enterprise Participation Sept. 1, 2000 June 1, 2004 * 80029 25 Disadvantaged Business Enterprise Participation Sept. 1, 2000 June 1, 2004 43761 26 Driving Guardrail Posts April 1, 1998 April 1, 1998 80100 27 Epoxy Coatings for Steel Reinforcement April 1, 1997 Jan. 1, 2003 80041 29 Epoxy Coating on Reinforcement April 1, 1997 Jan. 1, 2001 Aug. 1, 2003 80055 30 Erosion and Sediment Control Deficiency Deduction Aug. 1, 2001 Nov. 1, 2001 80101 32 Elagger Vests April 1, 2003 April 1, 2003 80072 34 Furnished Excavation Aug. 1, 2002 80073 35 Hand Vibrator Nov. 1, 2003 80103 36 Impact Attenuators, Temporary Nov. 1, 2003 80104 38 Inlet Filters Aug. 1, 2003 <td>80078</td> <td>21</td> <td>Controlled Aggregate Mixing System</td> <td></td> <td></td>	80078	21	Controlled Aggregate Mixing System		
80113 23 Curb Ramps for Sidewalk Jan. 1, 2004 80114 24 Curing and Protection of Concrete Construction Jan. 1, 2004 * 80029 25 Disadvantaged Business Enterprise Participation Sept. 1, 2000 June 1, 2004 43761 26 Driving Guardrail Posts April 1, 1998 April 1, 1997 Jan. 1, 2003 31578 28 Epoxy Coating on Reinforcement April 1, 1997 Jan. 1, 2003 80041 29 Epoxy Pavement Marking Jan. 1, 2001 Aug. 1, 2003 80055 30 Erosion and Sediment Control Deficiency Deduction Aug. 1, 2001 Nov. 1, 2001 80103 31 Expansion Joints Aug. 1, 2003 Nov. 1, 2003 80101 32 Flagger Vests April 1, 2003 April 1, 2003 80079 33 Freeze-Thaw Rating Nov. 1, 2002 Aug. 1, 2003 80079 34 Furnished Excavation Aug. 1, 2003 80079 35 Hand Vibrator Nov. 1, 2003 80010 36 Impact Attenuators, Temporary Nov. 1, 2003 <td>80102</td> <td>22</td> <td></td> <td></td> <td></td>	80102	22			
80114 24 Curing and Protection of Concrete Construction Jan. 1, 2004 * 80029 25 Disadvantaged Business Enterprise Participation Sept. 1, 2000 June 1, 2004 43761 26 Driving Guardrail Posts April 1, 1998 80100 27 Epoxy Coatings for Steel Reinforcement April 1, 1997 Jan. 1, 2003 31578 28 Epoxy Coating on Reinforcement April 1, 1997 Jan. 1, 2001 Aug. 1, 2001 80041 29 Epoxy Pavement Marking Jan. 1, 2001 Aug. 1, 2001 Aug. 1, 2003 80103 31 Expansion Joints Aug. 1, 2003 Nov. 1, 2003 Nov. 1, 2003 80103 31 Expansion Joints April 1, 2003 Nov. 1, 2002 April 1, 2003 80072 34 Furnished Excavation Aug. 1, 2002 Aug. 1, 2002 80074 35 Hand Vibrator Nov. 1, 2003 April 1, 2004 80103 36 Impact Attenuators, Temporary Nov. 1, 2003 April 1, 2004 80104 37 Intel Filters Nov. 1, 2002 Aug. 1, 2	80113	23		-	
* 80029 25 Disadvantaged Business Enterprise Participation Sept. 1, 2000 June 1, 2004 43761 26 Driving Guardrail Posts April 1, 1998 80100 27 Epoxy Coatings for Steel Reinforcement April 1, 1997 Jan. 1, 2003 31578 28 Epoxy Coating on Reinforcement April 1, 1997 Jan. 1, 2001 80041 29 Epoxy Pavement Marking Jan. 1, 2001 Aug. 1, 2003 80055 30 Erosion and Sediment Control Deficiency Deduction Aug. 1, 2001 Nov. 1, 2001 80103 31 Expansion Joints Aug. 1, 2003 80101 32 Flagger Vests April 1, 2003 80079 33 Freeze-Thaw Rating Nov. 1, 2002 80072 34 Furnished Excavation Aug. 1, 2002 80054 35 Hand Vibrator Nov. 1, 2003 80110 37 Impact Attenuators Nov. 1, 2003 80110 37 Impact Attenuators, Temporary Nov. 1, 2003 80104 38 Inlet Filters Aug. 1, 2003 80080 39 Insertion Lining of Pipe Culverts Nov. 1, 2002 80067 40 Light Emitting Diode (LED) Signal Head April 1	80114	24	·		
43761 26 Driving Guardrail Posts April 1, 1998 80100 27 Epoxy Coatings for Steel Reinforcement April 1, 2003 31578 28 Epoxy Coating on Reinforcement April 1, 1997 Jan. 1, 2001 80041 29 Epoxy Pavement Marking Jan. 1, 2001 Aug. 1, 2003 80055 30 Erosion and Sediment Control Deficiency Deduction Aug. 1, 2001 Nov. 1, 2003 80101 32 Flagger Vests April 1, 2003 80079 33 Freeze-Thaw Rating Nov. 1, 2002 80072 34 Furnished Excavation Aug. 1, 2002 80054 35 Hand Vibrator Nov. 1, 2003 80109 36 Impact Attenuators Nov. 1, 2003 80104 38 Inlet Filters Aug. 1, 2003 80104 38 Inlet Filters Aug. 1, 2003 80080 39 Insertion Lining of Pipe Culverts Nov. 1, 2002 80081 40 Light Emitting Diode (LED) Signal Head April 1, 2002 Aug. 1, 2003 80081 41 Lime Gradation Requirements Nov. 1, 2002 Aug. 1, 2003 80082 43 Multilane Pavement Patching Nov. 1, 2001 Aug.					June 1, 2004
80100 27 Epoxy Coatings for Steel Reinforcement April 1, 2003 31578 28 Epoxy Coating on Reinforcement April 1, 1997 Jan. 1, 2003 80041 29 Epoxy Pavement Marking Jan. 1, 2001 Aug. 1, 2003 80055 30 Erosion and Sediment Control Deficiency Deduction Aug. 1, 2003 Aug. 1, 2003 80103 31 Expansion Joints Aug. 1, 2003 80101 32 Flagger Vests April 1, 2003 80072 34 Furnished Excavation Aug. 1, 2002 80054 35 Hand Vibrator Nov. 1, 2003 80109 36 Impact Attenuators Nov. 1, 2003 80110 37 Impact Attenuators, Temporary Nov. 1, 2003 80080 39 Insertion Lining of Pipe Culverts Nov. 1, 2002 80081 40 Light Emitting Diode (LED) Signal Head April 1, 2002 Aug. 1, 2003 80081 41 Lime Gradation Requirements Nov. 1, 2002 Aug. 1, 2003 80082 43 Multilane Pavement Patching Nov.	43761	26		•	·
Special Spec	80100	27		•	
80041 29 Epoxy Pavement Marking Jan. 1, 2001 Aug. 1, 2003 80055 30 Erosion and Sediment Control Deficiency Deduction Aug. 1, 2001 Nov. 1, 2001 80103 31 Expansion Joints Aug. 1, 2003 April 1, 2003 80079 33 Flagger Vests April 1, 2002 80072 34 Furnished Excavation Aug. 1, 2002 80054 35 Hand Vibrator Nov. 1, 2003 80109 36 Impact Attenuators, Temporary Nov. 1, 2003 April 1, 2004 80104 38 Inlet Filters Aug. 1, 2003 80080 39 Insertion Lining of Pipe Culverts Nov. 1, 2002 Aug. 1, 2003 80081 41 Light Emitting Diode (LED) Signal Head April 1, 2002 Aug. 1, 2003 80082 43 Material Transfer Device June 15, 1999 March 1, 2001 80082 43 Multilane Pavement Patching Nov. 1, 2002 Aug. 1, 2003 80013 46 Pavement and Shoulder Resurfacing Feb. 1, 2000 Aug. 1, 2002	31578	28		•	Jan. 1, 2003
80055 30 Erosion and Sediment Control Deficiency Deduction Aug. 1, 2001 Nov. 1, 2001 80103 31 Expansion Joints Aug. 1, 2003 Aug. 1, 2003 80101 32 Flagger Vests April 1, 2003 April 1, 2002 80072 34 Furnished Excavation Aug. 1, 2002 80054 35 Hand Vibrator Nov. 1, 2003 80109 36 Impact Attenuators Nov. 1, 2003 80110 37 Impact Attenuators, Temporary Nov. 1, 2003 April 1, 2004 80104 38 Insertion Lining of Pipe Culverts Nov. 1, 2002 Aug. 1, 2003 80067 40 Light Emitting Diode (LED) Signal Head April 1, 2002 Aug. 1, 2003 80081 41 Lime Gradation Requirements Nov. 1, 2002 Aug. 1, 2003 80082 43 Multilane Pavement Patching Nov. 1, 2002 Aug. 1, 2003 80069 44 Organic Zinc-Rich Paint System Nov. 1, 2001 Aug. 1, 2003 80013 46 Partial Payments Sept. 1, 2003	80041	29			
80103 31 Expansion Joints Aug. 1, 2003 80101 32 Flagger Vests April 1, 2003 80079 33 Freeze-Thaw Rating Nov. 1, 2002 80072 34 Furnished Excavation Aug. 1, 2002 80054 35 Hand Vibrator Nov. 1, 2003 80109 36 Impact Attenuators Nov. 1, 2003 80110 37 Impact Attenuators, Temporary Nov. 1, 2003 April 1, 2004 80104 38 Inlet Filters Aug. 1, 2003 80080 39 Insertion Lining of Pipe Culverts Nov. 1, 2002 Aug. 1, 2003 80081 41 Light Emitting Diode (LED) Signal Head April 1, 2002 Aug. 1, 2003 80084 42 Material Transfer Device June 15, 1999 March 1, 2001 80082 43 Multilane Pavement Patching Nov. 1, 2002 Aug. 1, 2003 80016 45 Partial Payments Sept. 1, 2003 80013 46 Pavement and Shoulder Resurfacing Feb. 1, 2000 Aug. 1, 2002 <tr< td=""><td>80055</td><td>30</td><td></td><td></td><td>-</td></tr<>	80055	30			-
80101 32 Flagger Vests April 1, 2003 80079 33 Freeze-Thaw Rating Nov. 1, 2002 80072 34 Furnished Excavation Aug. 1, 2002 80054 35 Hand Vibrator Nov. 1, 2003 80109 36 Impact Attenuators Nov. 1, 2003 80110 37 Impact Attenuators, Temporary Nov. 1, 2003 April 1, 2004 80104 38 Inlet Filters Aug. 1, 2003 80080 39 Insertion Lining of Pipe Culverts Nov. 1, 2002 Aug. 1, 2003 80067 40 Light Emitting Diode (LED) Signal Head April 1, 2002 Aug. 1, 2003 80081 41 Lime Gradation Requirements Nov. 1, 2002 Aug. 1, 2003 80045 42 Material Transfer Device June 15, 1999 March 1, 2001 80082 43 Multilane Pavement Patching Nov. 1, 2002 Aug. 1, 2003 8016 45 Partial Payments Sept. 1, 2003 Aug. 1, 2003 8011 45 Pavement and Shoulder Resurfacing	80103	31	· · · · · · · · · · · · · · · · · · ·	-	
80079 33 Freeze-Thaw Rating Nov. 1, 2002 80072 34 Furnished Excavation Aug. 1, 2002 80054 35 Hand Vibrator Nov. 1, 2003 80109 36 Impact Attenuators Nov. 1, 2003 80110 37 Impact Attenuators, Temporary Nov. 1, 2003 April 1, 2004 80104 38 Inlet Filters Aug. 1, 2003 80080 39 Insertion Lining of Pipe Culverts Nov. 1, 2002 Aug. 1, 2003 80067 40 Light Emitting Diode (LED) Signal Head April 1, 2002 Aug. 1, 2003 80081 41 Lime Gradation Requirements Nov. 1, 2002 Aug. 1, 2003 80045 42 Material Transfer Device June 15, 1999 March 1, 2001 80082 43 Multilane Pavement Patching Nov. 1, 2002 Aug. 1, 2003 80116 45 Partial Payments Sept. 1, 2003 8011 46 Pavement and Shoulder Resurfacing Feb. 1, 2000 Aug. 1, 2002 53600 47 Pavement Thickness Determin	80101	32		April 1, 2003	
80072 34 Furnished Excavation Aug. 1, 2002 80054 35 Hand Vibrator Nov. 1, 2003 80109 36 Impact Attenuators Nov. 1, 2003 80110 37 Impact Attenuators, Temporary Nov. 1, 2003 April 1, 2004 80104 38 Inlet Filters Aug. 1, 2003 80080 39 Insertion Lining of Pipe Culverts Nov. 1, 2002 Aug. 1, 2003 80067 40 Light Emitting Diode (LED) Signal Head April 1, 2002 Aug. 1, 2003 80081 41 Lime Gradation Requirements Nov. 1, 2002 Aug. 1, 2003 80045 42 Material Transfer Device June 15, 1999 March 1, 2001 80082 43 Multilane Pavement Patching Nov. 1, 2002 Aug. 1, 2003 80116 45 Partial Payments Sept. 1, 2003 80013 46 Pavement and Shoulder Resurfacing Feb. 1, 2000 Aug. 1, 2002 53600 47 Pavement Thickness Determination for Payment April 1, 1999 Jan. 1, 2004 80022	80079	33			
80054 35 Hand Vibrator Nov. 1, 2003 80109 36 Impact Attenuators Nov. 1, 2003 80110 37 Impact Attenuators, Temporary Nov. 1, 2003 April 1, 2004 80104 38 Inlet Filters Aug. 1, 2003 80080 39 Insertion Lining of Pipe Culverts Nov. 1, 2002 Aug. 1, 2003 80067 40 Light Emitting Diode (LED) Signal Head April 1, 2002 Aug. 1, 2003 80081 41 Lime Gradation Requirements Nov. 1, 2002 80045 42 Material Transfer Device June 15, 1999 March 1, 2001 80082 43 Multilane Pavement Patching Nov. 1, 2002 Aug. 1, 2003 80069 44 Organic Zinc-Rich Paint System Nov. 1, 2001 Aug. 1, 2003 80116 45 Partial Payments Sept. 1, 2003 80013 46 Pavement and Shoulder Resurfacing Feb. 1, 2000 Aug. 1, 2002 53600 47 Pavement Thickness Determination for Payment April 1, 1999 Jan. 1, 2004 80022 48 Payment to Subcontractors June 1, 2000 Sept.	80072	34			
80110 37 Impact Attenuators, Temporary Nov. 1, 2003 April 1, 2004 80104 38 Inlet Filters Aug. 1, 2003 80080 39 Insertion Lining of Pipe Culverts Nov. 1, 2002 Aug. 1, 2003 80067 40 Light Emitting Diode (LED) Signal Head April 1, 2002 Aug. 1, 2003 80081 41 Lime Gradation Requirements Nov. 1, 2002 80045 42 Material Transfer Device June 15, 1999 March 1, 2001 80082 43 Multilane Pavement Patching Nov. 1, 2002 80069 44 Organic Zinc-Rich Paint System Nov. 1, 2001 Aug. 1, 2003 80116 45 Partial Payments Sept. 1, 2003 80013 46 Pavement and Shoulder Resurfacing Feb. 1, 2000 Aug. 1, 2002 53600 47 Pavement Thickness Determination for Payment April 1, 1999 Jan. 1, 2004 80022 48 Payment to Subcontractors June 1, 2000 Sept. 1, 2003	80054	35	Hand Vibrator		
80110 37 Impact Attenuators, Temporary Nov. 1, 2003 April 1, 2004 80104 38 Inlet Filters Aug. 1, 2003 80080 39 Insertion Lining of Pipe Culverts Nov. 1, 2002 Aug. 1, 2003 80067 40 Light Emitting Diode (LED) Signal Head April 1, 2002 Aug. 1, 2003 80081 41 Lime Gradation Requirements Nov. 1, 2002 80045 42 Material Transfer Device June 15, 1999 March 1, 2001 80082 43 Multilane Pavement Patching Nov. 1, 2002 80069 44 Organic Zinc-Rich Paint System Nov. 1, 2001 Aug. 1, 2003 80116 45 Partial Payments Sept. 1, 2003 80013 46 Pavement and Shoulder Resurfacing Feb. 1, 2000 Aug. 1, 2002 53600 47 Pavement Thickness Determination for Payment April 1, 1999 Jan. 1, 2004 80022 48 Payment to Subcontractors June 1, 2000 Sept. 1, 2003	80109	36	Impact Attenuators	Nov. 1, 2003	
80104 38 Inlet Filters Aug. 1, 2003 80080 39 Insertion Lining of Pipe Culverts Nov. 1, 2002 Aug. 1, 2003 80067 40 Light Emitting Diode (LED) Signal Head April 1, 2002 Aug. 1, 2003 80081 41 Lime Gradation Requirements Nov. 1, 2002 80045 42 Material Transfer Device June 15, 1999 March 1, 2001 80082 43 Multilane Pavement Patching Nov. 1, 2002 80069 44 Organic Zinc-Rich Paint System Nov. 1, 2001 Aug. 1, 2003 80116 45 Partial Payments Sept. 1, 2003 80013 46 Pavement and Shoulder Resurfacing Feb. 1, 2000 Aug. 1, 2002 53600 47 Pavement Thickness Determination for Payment April 1, 1999 Jan. 1, 2004 80022 48 Payment to Subcontractors June 1, 2000 Sept. 1, 2003				Nov. 1, 2003	April 1, 2004
80080 39 Insertion Lining of Pipe Culverts Nov. 1, 2002 Aug. 1, 2003 80067 40 Light Emitting Diode (LED) Signal Head April 1, 2002 Aug. 1, 2003 80081 41 Lime Gradation Requirements Nov. 1, 2002 80045 42 Material Transfer Device June 15, 1999 March 1, 2001 80082 43 Multilane Pavement Patching Nov. 1, 2002 80069 44 Organic Zinc-Rich Paint System Nov. 1, 2001 Aug. 1, 2003 80116 45 Partial Payments Sept. 1, 2003 80013 46 Pavement and Shoulder Resurfacing Feb. 1, 2000 Aug. 1, 2002 53600 47 Pavement Thickness Determination for Payment April 1, 1999 Jan. 1, 2004 80022 48 Payment to Subcontractors June 1, 2000 Sept. 1, 2003	80104	38			•
80067 40 Light Emitting Diode (LED) Signal Head April 1, 2002 Aug. 1, 2003 80081 41 Lime Gradation Requirements Nov. 1, 2002 80045 42 Material Transfer Device June 15, 1999 March 1, 2001 80082 43 Multilane Pavement Patching Nov. 1, 2002 80069 44 Organic Zinc-Rich Paint System Nov. 1, 2001 Aug. 1, 2003 80116 45 Partial Payments Sept. 1, 2003 80013 46 Pavement and Shoulder Resurfacing Feb. 1, 2000 Aug. 1, 2002 53600 47 Pavement Thickness Determination for Payment April 1, 1999 Jan. 1, 2004 80022 48 Payment to Subcontractors June 1, 2000 Sept. 1, 2003	80080	39	Insertion Lining of Pipe Culverts	-	Aug. 1, 2003
80081 41 Lime Gradation Requirements Nov. 1, 2002 80045 42 Material Transfer Device June 15, 1999 March 1, 2001 80082 43 Multilane Pavement Patching Nov. 1, 2002 80069 44 Organic Zinc-Rich Paint System Nov. 1, 2001 Aug. 1, 2003 80116 45 Partial Payments Sept. 1, 2003 80013 46 Pavement and Shoulder Resurfacing Feb. 1, 2000 Aug. 1, 2002 53600 47 Pavement Thickness Determination for Payment April 1, 1999 Jan. 1, 2004 80022 48 Payment to Subcontractors June 1, 2000 Sept. 1, 2003	80067	40			-
80045 42 Material Transfer Device June 15, 1999 March 1, 2001 80082 43 Multilane Pavement Patching Nov. 1, 2002 80069 44 Organic Zinc-Rich Paint System Nov. 1, 2001 Aug. 1, 2003 80116 45 Partial Payments Sept. 1, 2003 80013 46 Pavement and Shoulder Resurfacing Feb. 1, 2000 Aug. 1, 2002 53600 47 Pavement Thickness Determination for Payment April 1, 1999 Jan. 1, 2004 80022 48 Payment to Subcontractors June 1, 2000 Sept. 1, 2003		41			3
80069 44 Nov. 1, 2001 Organic Zinc-Rich Paint System Nov. 1, 2001 Aug. 1, 2003 80116 45 Partial Payments Sept. 1, 2003 80013 46 Pavement and Shoulder Resurfacing Feb. 1, 2000 Aug. 1, 2002 53600 47 Pavement Thickness Determination for Payment April 1, 1999 Jan. 1, 2004 80022 48 Payment to Subcontractors June 1, 2000 Sept. 1, 2003	80045	42	Material Transfer Device	June 15, 1999	March 1, 2001
80069 44 Nov. 1, 2001 Organic Zinc-Rich Paint System Nov. 1, 2001 Aug. 1, 2003 80116 45 Partial Payments Sept. 1, 2003 80013 46 Pavement and Shoulder Resurfacing Feb. 1, 2000 Aug. 1, 2002 53600 47 Pavement Thickness Determination for Payment April 1, 1999 Jan. 1, 2004 80022 48 Payment to Subcontractors June 1, 2000 Sept. 1, 2003	80082	43	Multilane Pavement Patching	Nov. 1, 2002	
80116 45 Partial Payments Sept. 1, 2003 80013 46 Pavement and Shoulder Resurfacing Feb. 1, 2000 Aug. 1, 2002 53600 47 Pavement Thickness Determination for Payment April 1, 1999 Jan. 1, 2004 80022 48 Payment to Subcontractors June 1, 2000 Sept. 1, 2003					Aug. 1, 2003
80013 46 Pavement and Shoulder Resurfacing Feb. 1, 2000 Aug. 1, 2002 53600 47 Pavement Thickness Determination for Payment April 1, 1999 Jan. 1, 2004 Payment to Subcontractors June 1, 2000 Sept. 1, 2003		45			<u>.</u>
53600 47 Pavement Thickness Determination for Payment April 1, 1999 Jan. 1, 2004 Payment to Subcontractors June 1, 2000 Sept. 1, 2003	80013	46			Aug. 1, 2002
80022 48 Payment to Subcontractors June 1, 2000 Sept. 1, 2003					
				•	

File	Name	<u>#</u>	Special Provision Title	Effective	Revised
	80119	50	Polyurea Pavement Marking	April 1, 2004	
*	80124		Portable Changeable Message Signs	Nov. 1, 1993	April 2, 2004
	80083		Portland Cement Concrete	Nov. 1, 2002	
	80036		Portland Cement Concrete Patching	Jan. 1, 2001	Jan. 1, 2004
	80095	54	Precast Block Revetment Mat	Jan. 1, 2003	
	419	55	Precast Concrete	July 1, 1999	Jan. 1, 2002
	80120	56	Precast, Prestressed Concrete Members	April 1, 2004	
	80084	57	Preformed Recycled Rubber Joint Filler	Nov. 1, 2002	
	80015		Public Convenience and Safety	Jan. 1, 2000	
	80121	59	PVC Pipeliner	April 1, 2004	
	80122		Railroad, Full-Actuated Controller	April 1, 2004	
	34261	61	Railroad Protective Liability Insurance	Dec. 1, 1986	May 1, 1988
	80105		Raised Reflective Pavement Markers (Bridge)	Aug. 1, 2003	A '' 4 0000
	80011	63	RAP for Use in Bituminous Concrete Mixtures	Jan. 1, 2000	April 1, 2002
	80032	64	Remove and Re-Erect Steel Plate Beam Guardrail and Traffic Barrier Terminals	Jan. 1, 2001	
	80085	65	Sealing Abandoned Water Wells	Nov. 1, 2002	
	80074	66	Shoulder Inlets with Curb	Aug. 1, 2002	
	80096	67	Shoulder Rumble Strips	Jan. 1, 2003	
	80070	68	Stabilized Subbase and Bituminous Shoulders Superpave	April 1, 2002	April 1, 2004
	80117	69	Stone for Erosion Protection, Sediment Control, and Rockfill	Jan. 1, 2004	
	80086	70	Subgrade Preparation	Nov. 1, 2002	
	80010	71	Superpave Bituminous Concrete Mixtures	Jan. 1, 2000	April 1, 2004
	80039	72	Superpave Bituminous Concrete Mixtures (Low ESAL)	Jan. 1, 2001	April 1, 2004
	80075	73	Surface Testing of Pavements	April 1, 2002	Aug. 1, 2003
	80092	74	Temporary Concrete Barrier	Oct. 1, 2002	Nov. 1, 2003
	80087		Temporary Erosion Control	Nov. 1, 2002	
	80008	76	Temporary Module Glare Screen System	Jan. 1, 2000	
	80106		Temporary Portable Bridge Traffic Signals	Aug. 1, 2003	
	80098		Traffic Barrier Terminals	Jan. 1, 2003	
	5729I	79	Traffic Control Deficiency Deduction	April 1, 1992	Jan. 1, 2003
	88008	80	Traffic Structures	Nov. 1, 2002	
	20338		Training Special Provisions	Oct. 15, 1975	
	80107	82	Transient Voltage Surge Suppression	Aug. 1, 2003	
	80123	83	Truck Bed Release Agent	April 1, 2004	
	80091		Underdrain Operations	Nov. 1, 2002	
	80048	85	Weight Control Deficiency Deduction	April 1, 2001	Aug. 1, 2002
*	80090	86	Work Zone Public Information Signs	Sept. 1, 2002	April 2, 2004
*	80125		Work Zone Speed Limit Signs	April 2, 2004	
*	80126		Work Zone Traffic Control	April 2, 2004	
*	80097		Work Zone Traffic Control Devices	Jan. 1, 2003	April 2, 2004
	80071	90	Working Days	Jan. 1, 2002	

The following special provisions have been **deleted** from use:

80056 Placement of Arrow Boards This special provision has been made obsolete by revisions made to the Highway Standards.

<u>80038 Sand Module Impact Attenuators</u> This special provision has been replaced by the special provisions, "Impact Attenuators" and "Impact Attenuators, Temporary". Maintenance contracts for replacement of permanent impact attenuators will require a district special provision.

<u>80068 Material Allowances</u> The contents of this special provision have been included in the new special provision, "Partial Payments".

<u>80115 Mobilization</u> This special provision was pulled before the January 16, 2004 letting. The version currently shown in the 2004 Supplemental Specifications is still valid.

The following special provisions have been **moved**:

80025 Fluorescent Orange Sheeting on Drums This special provision has been combined with BDE 80097, Work Zone Traffic Control Devices.

80089 Vertical Barricades This special provision has been combined with BDE 80097, Work Zone Traffic Control Devices.

The following special provisions are in the 2004 Supplemental Specifications and Recurring Special Provisions:

File Name	Special Provision Title	New Location	<u>Effective</u>	<u>Revised</u>
21982	Pavement Removal	Section 440	Jan. 1, 1999	Nov. 1, 2001

The following special provisions require additional information from the designer. The additional information needs to be included in a separate document attached to this check sheet. The Project Development and Implementation section will then include the information in the applicable special provision. The Special Provisions are:

- Building Removal-Case I
- Building Removal-Case II
- Building Removal-Case III
- Building Removal-Case IV
- DBE Participation
- Material Transfer Device
- Railroad Protective Liability Insurance
- Training Special Provisions
- Working Days